

VCCI Council

## **Acceptance of Report of Compliance**

Company name: Intel K.K.

Address: 東京都千代田区丸の内3-1-1 国際ビル5階

Responsible personIvory,BrianMember number:338Department:Intel CPRS WW teamReport No.:2019078814E-mail:brian.ivory@intel.comReporting date:2020/01/14Contact personChaoyong,LONGReporting media:online

Address: 17F, Tower 3, YinTai Center, No. 1199 Tianfu Avenue North, Hi-Tech Zone, Chengdu, China,610014

Department: Intel CPRS WW Status: accepted

Phone: +8613709056688 Last report No.:

FAX: N.A Acceptance No.: 2019055178

E-mail: chaoyong.long@intel.com Sub No.: 1

Recipient of Acceptance Notice Acceptance date: 2020/01/14

Department: Intel CPRS WW

E-mail: chaoyong.long@intel.com

Reporting type:	new			
Applied VCCI Rule:	VCCI 32-1			
Classification of Equipment and classification code:		ClassB / Classification code b2		
General Name of Equipment:	Desktop PC			
Product type (Model No.):	NUC8PNK			
Member number of a test laboratory:	Audix Technology (WuJiang) Co., Ltd.			
Name of the testing laboratory:				
Measurement facility registration number:	Measurement item and Registration No. of Testing facility.		Measurement distance/Reason why not applicable	
	Radiated EMI measurement below 1GHz facility		R-12436	10 m
	2. Radiated EMI measurement above 1GHz facility		G-20050	3 m
	3. Mains port conducted EMI measurement facility		C-12666	
	4. Conducted EMI measurement for Wired Network port, etc (including Tuner port, Antenna port, etc)		T-11644	
	5. Article 15 registered laboratory		A-	
	6. This compliance verification test was conducted at the installation site of users.			
Date of testing:	2019/09/03			
Serial No. of the test report:	ACWE-V1910001			
Reason for				
addition/modification:				
VCCI comment:				