



VCCI Council

Acceptance of Report of Compliance

Company name: Intel K.K.
 Address: 東京都千代田区丸の内3-1-1 国際ビル5階
 Responsible person Lillian Li
 Department: Corporate Product Regulation Standards
 E-mail: lillian.l.li@intel.com
 Contact person Lillian Li
 Address: 2200 Mission College BLVD, Santa Clara CA 95054
 Department: CISD
 Phone: 5036962691
 FAX: 5036962349
 E-mail: lillian.l.li@intel.com
 Recipient of Acceptance Notice
 Department: Corporate Product Regulation Standards
 E-mail: lillian.l.li@intel.com

Member number: 338
 Report No.: 2017065537
 Reporting date: 2018/03/09
 Reporting media: online
 Status: accepted
 Last report No.:
 Acceptance No.: 2017046014
 Sub No.: 1
 Acceptance date: 2018/03/09

Reporting type:	new		
Applied VCCI Rule:	VCCI 32-1		
Classification of Equipment and classification code:	ClassB / Classification code b2		
General Name of Equipment:	Intel NUC		
Product type (Model No.):	xNUC8xCYx		
Member number of a test laboratory:	237	Audix Technology Corporation	
Name of the testing laboratory:	Audix Technology Corporation		
Measurement facility registration number:	Done		Measurement distance
	1) Radiated EMI measurement below 1GHz facility	R-3918	10 m
	2) Radiated EMI measurement above 1GHz facility	G-10628	3 m
	3) Mains port conducted EMI measurement facility	C-4426	
	4) Wired network port and other port Conducted EMI measurement facility	T-1411	
	5) Article 15 registered laboratory	A-	
	6) This compliance verification test was conducted at the installation site of users.		
Date of testing:	2017/12/08 2017/12/11		
Serial No. of the test report:	EM-V170273		
Reason for addition/modification:			
VCCI comment:			