

VCCI Council

Acceptance of Report of Compliance

Company name: Intel K.K.

Address: 東京都千代田区丸の内3-1-1 国際ビル5階

Responsible person Ivory,Brian Member number: 338

Department: Intel CPRS WW team Report No.: 2021093066
E-mail: brian.ivory@intel.com Reporting date: 2021/11/03
Contact person Chaoyong,LONG Reporting media: online

Address: 17F, Tower 3, YinTai Center, No. 1199 Tianfu Avenue North, Hi-Tech Zone, Chengdu, China,610014

Department: Intel CPRS WW Status: accepted

Phone: +8613709056688 Last report No.:

FAX: N.A Acceptance No.: 2021065302

E-mail: chaoyong.long@intel.com Sub No.: 1

Recipient of Acceptance Notice Acceptance date: 2021/11/04

Department: Intel CPRS WW

E-mail: chaoyong.long@intel.com

Classification of Equipment code: General Name of Equipment: Product type (Model	esktop PC JC11ATK	ClassB / Classification	n code b2				
code: General Name of Equipment: Product type (Model NI	esktop PC JC11ATK	ClassB / Classification	n code b2				
Equipment: Product type (Model NI	JC11ATK						
	I			Desktop PC			
	_	NUC11ATK					
Member number of a test laboratory: 237	237 Audix Technology Corporation						
Name of the testing laboratory:							
	Measurement item and Registration No. of Testing facility.			Measurement distance/Reason why not applicable			
	Radiated EMI measurement below 1GHz facility		R-20065	10 m			
	Radiated EMI measurement above 1GHz facility		G-20064	3 m			
registration number: [3.1]	3. Mains port conducted EMI measurement facility		C-14426				
Ne	4. Conducted EMI measurement for Wired Network port, etc (including Tuner port, Antenna port, etc)		T-11411				
5. 4	5. Article 15 registered laboratory A-		A-				
	6. This compliance verification test was						
	conducted at the installation site of users.						
	21/08/18						
Serial No. of the test report:	M-V210199						
Reason for addition/modification:							
VCCI comment:							